

APPENDIX D

PHOTOGRAPHIC DOCUMENTATION

RESOURCE RECOVERY CORPORATION  
PASCO, WASHINGTON

SITE INSPECTION - 9/12/84

COMPILED BY  
ECOLOGY AND ENVIRONMENT, INC.  
SEATTLE, WASHINGTON

USEPA SF



1452483

# PHOTO IDENTIFICATION SHEET

Type of Camera: Nikon FM

TDD No.: 10-8408-22

Type of Film: Kodachrome

Resource Recovery Corporation, Pasco WA

EPA No.: \_\_\_\_\_

Photo No.	Date	Time	Taken by	Description of Photo
1	9/12/84	0750	Rich Brooks	Entrance Gate taken in N-NW direction
2	"	0830	" "	Waste Disposal Area A - taken in S direction
3	"	0835	" "	Waste Disposal Area C&D - taken in E direction
4	"	0840	" "	Waste Disposal Area C&D - taken in E direction
5	"	0845	" "	Waste Disposal Area C&D - taken in E direction
6	"	0850	" "	Dry Well - taken in SW direction
7	"	0855	" "	Waste Disposal Area E & Dry Well - taken in NE direction
8	"	0900	" "	Waste Disposal Area E - taken in NW direction
9	"	0905	" "	Sewage Lagoons - taken in E direction
10	"	0910	" "	Waste Disposal Area B - taken in E direction
11	"	0915	" "	Waste Disposal Area B & Sensor - taken in N direction
12	"	0920	" "	Wide Angle of Whole Site - taken in S direction



Type of Camera: Nikon FM  
Type of Film: Kodachrome

Resource Recovery Corporation, Pasco WA EPA No.:

[illegible]

# TARGET SHEET: Oversized Document

**This document was not imaged due to the original being oversized. Oversized documents are located at the Superfund Records Center. Please contact the Records Center Help Desk at 206-553-4494 for assistance.**

If this oversized material is part of another document, fill out below information:

**This oversized document is a part of Doc ID:**

**Oversized Document Title (if any):**

15 SLIDES.



Region 10  
1200 Sixth Ave.  
Seattle, WA 98101